### **ENVIRONMENTAL CHEMISTS**

Date of Report: 09/08/08 Date Received: 08/18/08

Project: Stormwater, PO M120311, F&BI 808169

Date Analyzed: 08/19/08

# RESULTS FROM THE ANALYSIS OF WATER SAMPLES FOR pH USING EPA METHOD 9040C

<u>Sample ID</u>
Laboratory ID

M120311D
808169-04

7.1

### **ENVIRONMENTAL CHEMISTS**

Date of Report: 09/08/08 Date Received: 08/18/08

Project: Stormwater, PO M120311, F&BI 808169

Date Analyzed: 08/19/08

# RESULTS FROM THE ANALYSIS OF WATER SAMPLES FOR TURBIDITY USING METHOD SM2130B

Results Reported as NTU

Sample ID Laboratory ID	Date <u>Sampled</u>	Time <u>Sampled</u>	Turbidity
M120311D 808169-04	08/18/08	1250	34
Method Blank			<0.5

### **ENVIRONMENTAL CHEMISTS**

### Analysis For Total Metals By EPA Method 200.8

Client ID: M120311B

Date Received: 08/18/08

Date Extracted: 08/19/08

Date Analyzed: 08/21/08

Matrix: Water

Units: ug/L (ppb)

Lab ID: Data File: Instrument: Operator:

Client:

Project:

PO M120311, F&BI 808169 808169-02 808169-02.009

Alaskan Copper Works

ICPMS1 hr

Internal Standard:

% Recovery: 95

Lower Limit: 60 Upper Limit: 125

Concentration

Analyte:

Holmium

ug/L (ppb)

Lead

28.2

### **ENVIRONMENTAL CHEMISTS**

### Analysis For Total Metals By EPA Method 200.8

Client ID: M120311C
Date Received: 08/18/08
Date Extracted: 08/19/08
Date Analyzed: 08/21/08
Matrix: Water
Units: ug/L (ppb)

Lab ID:
Data File:
Instrument:
Operator:

Client:

Project:

Lower Upper Limit: Limit: 60 125

hr

808169-03

808169-03 .010 ICPMS1

Alaskan Copper Works PO M120311, F&BI 808169

Germanium
Analyte:

Internal Standard:

ug/L (ppb)

% Recovery:

106

Concentration

 Copper
 403

 Zinc
 1,200 jl

#### **ENVIRONMENTAL CHEMISTS**

# Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: NA
Date Extracted: 08/19/08
Date Analyzed: 08/21/08
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: PO M120311, F&BI 808169
Lab ID: I8-322 mb
Data File: I8-322 mb.008
Instrument: ICPMS1
Operator: hr

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 97 60 125 Holmium 97 60 125

Concentration

Analyte: ug/L (ppb)

Copper <1
Zinc <1 jl
Lead <1

### **ENVIRONMENTAL CHEMISTS**

Date of Report: 09/08/08 Date Received: 08/18/08

Project: Stormwater, PO M120311, F&BI 808169

# QUALITY ASSURANCE RESULTS FROM THE ANALYSIS OF WATER SAMPLES FOR pH BY METHOD 9040C

Laboratory Code: 808169-04 (Duplicate)

	Sample Duplicate		Relative Percent	Acceptance
Analyte	Result	Result	Difference	Criteria
pН	7.10	7.20	1.4	0-20

### **ENVIRONMENTAL CHEMISTS**

Date of Report: 09/08/08 Date Received: 08/18/08

Project: Stormwater, PO M120311, F&BI 808169

### QUALITY ASSURANCE RESULTS FROM THE ANALYSIS OF WATER SAMPLES FOR TURBIDITY USING METHOD SM2130B

Laboratory Code: 808169-04 (Duplicate)

Analyte	Reporting	Sample	Duplicate	Percent	Acceptance	
	Units	Result	Result	Difference	Criteria	
Turbidity	NTU	33.8	33.3	Della Ta	0-20	

#### **ENVIRONMENTAL CHEMISTS**

Date of Report: 09/08/08 Date Received: 08/18/08

Project: Stormwater, PO M120311, F&BI 808169

## QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 808161-01 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria	
Copper	ug/L (ppb)	1.04	<1	nm	0-20	7
Zinc	ug/L (ppb)	2.52	2.48	2	0-20	
Lead	ug/L (ppb)	<1	<1	nm	0-20	

Laboratory Code: 808161-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Acceptance Criteria
Copper	ug/L (ppb)	20	1.04	92	50-150
Zinc	ug/L (ppb)	50	2.52	95	50-150
Lead	ug/L (ppb)	10	<1	104	50-150

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria
Copper	ug/L (ppb)	20	<1	70-130
Zinc	ug/L (ppb)	50	65 vo	70-130
Lead	ug/L (ppb)	10	99	70-130

#### **ENVIRONMENTAL CHEMISTS**

# **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr- The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

#### **ENVIRONMENTAL CHEMISTS**

### CASE NARRATIVE

This case narrative encompasses samples received on August 18, 2008 by Friedman & Bruya, Inc. from the Alaskan Copper Works Stormwater, PO M120311, F&BI 808169 project. Samples were logged in under the laboratory ID's listed below.

Laboratory ID	Alaskan Copper Works			
808169-01	M120311A			
808169-02	M120311B			
808169-03	M120311C			
808169-04	M120311D			

Sample M120311A was sent to Aquatic Research for oil and grease analysis. In addition, sample M120311B was sent to Aquatic Research for hardness analysis. Review of the enclosed report indicates that all quality assurance was acceptable.

All quality control requirements were acceptable.



LABORATORY & CONSULTING SERVICES 3927 AURORA AVENUE NORTH, SEATTLE, WA 98103 PHONE: (206) 632-2715 FAX: (206) 632-2417

CASE FILE NUMBER:

FBI002-84

PAGE 1

REPORT DATE: DATE SAMPLED: 09/02/08

08/18/08

**DATE RECEIVED:** 

08/20/08

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM FRIEDMAN & BRUYA, INC. / PROJECT NO. 808169

#### **CASE NARRATIVE**

Two water samples were received by the laboratory in good condition. Analysis was performed according to the chain of custody received with the samples. No difficulties were encountered in the preparation or analysis of these samples. Sample data follows while QA/QC data is contained on the following page.

#### SAMPLE DATA

SILIVII DD DILIII		
	FOG	HARDNESS
SAMPLE ID	(mg/l)	(mgCaCO3/l)
M120311A	12.6	
M120311B		76.0



LABORATORY & CONSULTING SERVICES 3927 AURORA AVENUE NORTH, SEATTLE, WA 98103 PHONE: (206) 632-2715 FAX: (206) 632-2417

CASE FILE NUMBER:

FBI002-84

PAGE 2

REPORT DATE:

09/02/08

DATE SAMPLED:

08/18/08

**DATE RECEIVED:** 

08/20/08

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM FRIEDMAN & BRUYA, INC. / PROJECT NO. 808169

#### QA/QC DATA

QC PARAMETER	FOG HARDNE	
	(mg/l)	(mgCaCO3/l)
METHOD	EPA 1664	EPA 130.2
DATE ANALYZED	08/29/08	08/29/08
DETECTION LIMIT	2.00	2.00
DUPLICATE		
SAMPLE ID		BATCH
ORIGINAL		49.3
DUPLICATE		49.6
RPD	NA	0.79%
SPIKE SAMPLE SAMPLE ID	WANTE .	ватсн
ORIGINAL		49.3
SPIKED SAMPLE		68.6
SPIKE ADDED	b	20.0
% RECOVERY	NA	96.74%
QC CHECK		30.7770
FOUND	7.50	39.5
TRUE	8.00	40.0
% RECOVERY	93.75%	98.70%
		5
BLANK	<2.00	<2.00

RPD = RELATIVE PERCENT DIFFERENCE.

NA = NOT APPLICABLE OR NOT AVAILABLE. NC = NOT CALCULABLE DUETO ONE OR MORE VALUES BEING BELOW THE DETECTION LIMIT.

OR = RECOVERY NOT CALCULABLE DUE TO SPIKE SAMPLE OUT OF RANGE OR SPIKE TO LOW RELATIVE TOO SAMPLE CONCENTRATION

### SUBMITTED BY:

Steven Lazoff Laboratory Director

### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com



September 8, 2008

### **INVOICE #08ACU0908-1**

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Stormwater, PO M120311, F&BI 808169 - Results of testing requested by Gerry Thompson for material submitted on August 18, 2008.

1 sample analyzed for Turbidity by Method SM214A @ \$22 per sample	\$ 22.00
1 sample analyzed for Total Zn and Cu by Method 200.8 @ \$50 per sample	50.00
1 sample analyzed for pH by Method 9040C @ \$25 per sample	25.00
1 sample analyzed for Oil and Grease by Method 1664 @ \$85 per sample	85.00
1 sample analyzed for Total Lead by Method 200.8 @ \$30 per sample	30.00
1 sample analyzed for Hardness by Method SM2340 @ \$35 per sample	35.00
Amount Due	\$ 247.00

FEDERAL TAX ID #(b) (6)

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

September 8, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on August 18, 2008 from the Stormwater, PO M120311, F&BI 808169 project. There are 10 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0908R.DOC



LABORATORY & CONSULTING SERVICES

 $3927\ AURORA\ AVENUE\ NORTH,\ SEATTLE,\ WA\ 98103$ 

PHONE: (206) 632-2715

FAX: (206) 632-2417

**CASE FILE NUMBER:** 

FBI002-84

PAGE 1

REPORT DATE: DATE SAMPLED:

09/02/08 08/18/08

DATE RECEIVED:

08/20/08

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM FRIEDMAN & BRUYA, INC. / PROJECT NO. 808169

#### **CASE NARRATIVE**

Two water samples were received by the laboratory in good condition. Analysis was performed according to the chain of custody received with the samples. No difficulties were encountered in the preparation or analysis of these samples. Sample data follows while QA/QC data is contained on the following page.

#### SAMPLE DATA

	FOG	HARDNESS
SAMPLE ID	(mg/l)	(mgCaCO3/l)
M120311A	12.6	
M120311B		76.0



LABORATORY & CONSULTING SERVICES

3927 AURORA AVENUE NORTH, SEATTLE, WA 98103 PHONE: (206) 632-2715 FAX: (206) 632-2417

**CASE FILE NUMBER:** 

FBI002-84

PAGE 2

REPORT DATE:

09/02/08

**DATE RECEIVED:** 

08/20/08

DATE SAMPLED:

08/18/08

FINAL REPORT, LABORATORY ANALYSIS OF SELECTED PARAMETERS ON WATER

SAMPLES FROM FRIEDMAN & BRUYA, INC. / PROJECT NO. 808169

### QA/QC DATA

FOG	HARDNESS
(mg/l)	(mgCaCO3/l)
EPA 1664	EPA 130.2
08/29/08	08/29/08
2.00	2.00
	ВАТСН
	49.3
	49.6
NA	0.79%
	ВАТСН
	49.3
	68.6
	20.0
NA	96.74%
7.50	39.5
8.00	40.0
93.75%	98.70%
< 2.00	< 2.00
	(mg/l) EPA 1664 08/29/08 2.00  NA  NA  7.50 8.00 93.75%

RPD ≈ RELATIVE PERCENT DIFFERENCE.

NA = NOT APPLICABLE OR NOT AVAILABLE.

NC = NOT CALCULABLE DUE TO ONE OR MORE VALUES BEING BELOW THE DETECTION LIMIT.

OR = RECOVERY NOT CALCULABLE DUE TO SPIKE SAMPLE OUT OF RANGE OR SPIKE TO LOW RELATIVE TOO SAMPLE CONCENTRATION.

SUBMITTED BY:

Laboratory Director

# SUBCONTRACT SAMPLE CHAIN OF CUSTODY

Send Report To Michael Erdahl	SUBCONTRACTER		Page # of TURNAROUND TIME
CompanyFriedman and Bruya, Inc	PROJECT NAME/NO.	PO#	Standard (2 Weeks)     □ RUSH
Address 3012 16th Ave W	808169	H-1516	Rush charges authorized by:
City, State, ZIP Seattle, WA 98119	REMARKS	SAMPLE DISPOSAL  □ Dispose after 30 days	
Phone #(206) 285-8282Fax #(206) 283-5044	Please Email Results merdahl@friedmanandbruya.com	☐ Return samples☐ Will call with instructions	

						ANALYSES REQUESTED								ž.		
Sample ID	Lab ID	Date Sampled	Time Sampled	Matrix	# of jars	Oil and Grease	ВРН	VPH	Nitrate	Sulfate	Alkalinity	Hardness				Notes
M120311A		8/18/05	12:50	W	1	×										
M120311B		\ \	Ţ	w							CO LIE-SVI	×				
					115											
	3,							U.								
									ĺ		İ					
		İ												Ì		
	1									İ	İ				İ	

Friedman & Bruya, Inc. 3012 16th Avenue West

Seattle, WA 98119-2029

Ph. (206) 285-8282

Fax (206) 283-5044

SIGNATURE	PRINT NAME	COMPANY	DATE	TIME
Relinquished by	Michael Erdahl	Friedman & Bruya	8/19/09	1:45
Received by	S. NIECSCK	MR.I	8/20/18	1400
Relinquished by:	¥ 1			
Received by:				

808169	8 8 8	35 1 1 1 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	SAI	SAMPLE CHAIN OF CUSTODY HE 08/18											108 AIG							
	<u> </u>	. 05-	3.50 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1	SAMPLERS (signature)													ago #	of _ D TII				
Company ALASKA Address 628 S		Meson was	seks	PROJECT NAME/NO.									)# 03	11	0	Stan RUS ush c						
City, State, ZIP Sear	State, ZIP <u>Seattle</u> who 28134 e#DOLS71-6033 Fax#26-787-430f						REMARKS									Disp Retu	ose a	after 30 d amples	PLE DISPOSAL fter 30 days mples vith instructions			
	1					·				E			SES REQUESTED									
Sample ID	Sample ID Lab ID Date Time		Time	Sam	ple Type	# of containers	TPH-Diesel TPH-Gasoline		BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS OX ranese		HARDNOS/POTAL PB	76 Cu/20	PH Tuebicity			Notes			
m120311 A	01	8/18/08	12:50	TH	20	1							$\downarrow$					F05				
5 5				WI .																		
MROBILB	. 02	8/18/08	12:50	H;	20						1			メ				19 (H)	)			
13													_									
MIZOSILC	03	8/18/08	12:50	1 1	120					1					X			COTTO	<u>)</u>	,		
M12031D	04	8/18/08	12:50	11.	CS			-	-		+	-				X	_	ANT.	)			
7 11200110		710190	10.5	1	20			$\dagger$			1							Tin.		-//		
		12																				
Friedman & Bruya, Inc. 3012 16th Avenue West	Relinantina	SIGNATU	RE	PRINT NAME								COMPANY						DATE	_	TIME		
Seattle, WA 98119-2029 Received by:					19han Phan											<b>-</b>	- 6	8/8/08	1	126Ph		
Ph. (206) 285-8282	m an au						ai	<u> </u>			+	FeBT						118/0	2	طه		
Fox (206) 283-5044	Received by:											Zam	nla	á vbí	eive	da	t コユ	<del> c</del>	- 3-1			

FORMS\COC\COC.DOC